

Oil Field Environmental Incident Summary

Incident: 20140906223725 **Date/Time of Notice:** 09/06/2014 22:37
Responsible Party: SHD OIL & GAS, LLC
Well Operator: SHD OIL & GAS, LLC
Well Name: HAMMER 12-36H
Field Name: CLARKS CREEK **Well File #:** 27039
Date Incident: 9/6/2014 **Time Incident:** 00:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 151 **Rng:** 95 **Sec:** 36 **Qtr:**
Location Description:

Submitted By: Randy Neset **Received By:**
Contact Person: Randy Neset
6844 Highway 40
Tioga, ND 58852

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Tank Leak

	Spilled	Units	Recovered	Units	Reported to NRC:	Followup	Units
Oil					No		
Brine	40	Barrels	40	Barrels			
Other			20	Barrels			

Description of Other Released Contaminant:

Rainwater

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Hatch of water upright was sealed and vacuum truck was utilized to recover brine from containment unit and area immediately surrounding tank battery and containment unit

Wastes Disposal Location: Brine recovered inside of containment unit was placed back in water upright and materials vacuumed surrounding the tanks were cycled into drilling mud.

Agencies Involved:

Updates

Date: 9/8/2014

Status: Reviewed; O&G Lead

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank leak, remained on location within the diking according to the report. NDIC retains oversight.